If you are using a printed copy of this procedure, and not the on-screen version, then you <u>MUST</u> make sure the dates at the bottom of the printed copy and the on-screen version match.

The on-screen version of the Collider-Accelerator Department Procedure is the Official Version. Hard copies of all signed, official, C-A Operating Procedures are kept on file in the C-A ESHQ Training Office, Bldg. 911A

C-A OPERATIONS PROCEDURES MANUAL

14.6.1 Operational Control Form for Electronic Assembly Operations

Text Pages 2 through 3

Hand Processed Changes

HPC No.	<u>Date</u>	Page Nos.	<u>Initials</u>
	Approved:	Signature on File	
		er-Accelerator Department Cha	nirman Date

M. Van Essendelft

14.6.1 Operational Control Form for Electronic Assembly Operations

BNL Environmental Management System Operational Control Form

Operational Control	Completed By: M. Van Essendelft
For Significant Environmental Aspects	
	Date: February, 2006
AGS-010-EAO	•

1. Operation(s):

Electronic Assembly and Repair (Bldgs. 911, 919B, 923, 1007W)

2. Activity(ies):

- Hazardous Waste generation
- Atmospheric discharges
- Radioactive waste generation

3. Operational Controls (technological, operational, procedural operating criteria):

- Satellite Accumulation Area for waste
- OPM 8.20, Handling and Disposing of Hazardous Waste
- OPM 8.20.2, Radioactive Waste Disposal
- OPM 8.22, Handling and Disposal of Non-Hazardous and Recyclable Solid Waste
- OPM 2.28, C-A Procedure for Work Planning and Control for Operations
- Tier I program and self-assessments
- Chemical Management System
- OPM 8.20.1, C-A Hazardous Waste Trailer (HWT) (90-Day Accumulation Area)
- OPM 1.15, Liquid and Airborne Effluents

4. Maintenance Plan(s):

N/A

5. Actions to be Taken if Control Fail:

- Call spill response hotline 2222 or 911
- See C-A OPM 3.0, Local Emergency Plan for the C-A Department
- OPM 10.1, Occurrence Reporting and Processing of Significant Operations Information

6. Records

- Tier I Inspection records / Tracking Database
- Operational Control Form
- Process Assessment Form / Corrective Action, P2 Measures, and Assessment, Prevention & Control Initiatives Tracking Database
- C-A Family ATS documentation on completion of Environmental Management Program, Section 10 Tasks
- ORPS report (for qualifying liquid spill only)
- Satellite Area inspections records
- **7. Responsibilities**: [(a) to ensure controls are in place; (b) to ensure controls keep working; (c) to take action when controls fail; (d) to create and keep records relative to operational controls

Name	Responsibility	
Electronic assembly group supervisors	Ensure segregation of waste, maintain Satellite Accumulation Areas (if applicable)	
Tier I Inspection Committee	Tier I documentation	
C-A Waste Management Representative	Satellite Area inspections	

8. Training:

Name	Training	Date
Electronic assembly group	Hazardous Waste generator	N/A
supervisors	Radioactive Waste generator	
Video repair shop supervisor	Hazardous Waste generator	N/A
	Radioactive Waste generator	
Building Staff	See also: EMS Training package for this operation	N/A